

# NIAS Donning Mpx Airborne Precautions PPE



## PPE Required

- FFP3 mask – do fit check
- Coverall suit ensuring full coverage of face and uniform
- Full visor
- 1 pair standard gloves
- Apron

## Donning Procedure

### Perform Hand Hygiene

**Step 1:** Put on your disposable FFP3 respirator and check for fit.

This **MUST** be the mask that you are fit tested to.



**Step 2:** Don Fluid Repellent Coverall



**Step 3:** Put on apron



**Step 4:** Put on Full face Visor



**Step 5:** Put on a standard pair of gloves

Ensure glove cuffs overlap sleeves of the coverall suit.



